

VLS-08-20



The VLS-08-20's that have the software issue will have the following P/N and rev on the front of the unit...

42000005 REV K
under the Anver Logo

On the Bottom of the unit it will have the following info on the label...

P/N 42000005-rev K
Software: 38000018 rev F software

VLS-08



The VLS-08's that have the software issue will have the following P/N and rev on the front of the unit...

42000004 REV K
under the Anver Logo.

On the Bottom of the unit it will have the following info on the label....

P/N 42000004-rev K
Software: 38000018 rev F software